



SERVICE BULLETIN

Subject: NON-REFLECTIVE TAPE FOR SENSOR COVERS
Applicable Products: S AND K SERIES LIFTS
Effective Date: 03-10-06

Ricon service bulletins are for use by professional service technicians, and are not intended for use by non-professionals or amateurs. Service bulletins alert technicians to issues that may occur with Ricon products, and are intended to assist the technician in the proper service of those products.

Professional service technicians have the background and knowledge to perform maintenance work properly and safely.

An issue described by a service bulletin does not necessarily apply to every unit in a product line. A Ricon authorized service technician will be able to determine which units can benefit from the information provided here.

Implementation:

Ricon recommends the incorporation of this service bulletin when an object placed very close to an optical sensor does not activate the Threshold Warning System.

Caution:

Corrective Action: Installation Non-reflective tape.

Parts Involved: Kit # 35707. The kit can be ordered by calling 1-800-322-2884, please have lift Serial number available.




Figure [1] NON-REFLECTIVE TAPE PREP STAGE




Figure [2] NON-REFLECTIVE TAPE INSTALLED
AS NOTED IN THE TEXT ABOVE THIS SHOULD BE DONE ON
BOTHSIDES OF THE LIFT. THE SECTIONS FACING THE
BRIDGE PLATE SHOULD BE THE ONLY SURFACES
REQUIRING THESE ADDITIONS.