



SERVICE BULLETIN

Subject: Upgrades
Applicable Products: S AND K SERIES LIFTS
Effective Date:

Ricon service bulletins are for use by professional service technicians, and are not intended for use by non-professionals or amateurs. Service bulletins alert technicians to issues that may occur with Ricon products, and are intended to assist the technician in the proper service of those products.

Professional service technicians have the background and knowledge to perform maintenance work properly and safely.

An issue described by a service bulletin does not necessarily apply to every unit in a product line. A Ricon authorized service technician will be able to determine which units can benefit from the information provided here.

Implementation: None




Figure [1] New parts

- New parts added to lift to make installation easier.



Figure [2] New cutouts in pump cover

- These new cutouts will make lift installation faster. We are adjusting the limit switches at the factory. Most of the time there will be no need to readjust.
- No need to remove pump cover.



Figure [3] Pressure switch

- Now there is an access hole in the cover, no need to remove the cover to adjust the pressure switch.



Figure [4] Bridgeplate

- Added to the bridgeplate are adjusting holes for cables.



Figure [5] Non-skid tape

- Added to the rear of the platform is a strip of grey non-skid tape.



Figure [6] Reflector tape

- We add reflector tape down the complete edge of both sides of the platform.